

MACH3 USB Steel Structure 6040

3axis/4axis Packing List





Packing list(pics):



CNC 6040 **3axis machine** , Packing list as blow:

1	Water pump* 2	5	Power Cable * 1	9	Engraving bits * 5 4F*6*6*19*63mm White steel bit * 1 4F*6*6*15*50mm Tungsten steel milling bit * 1 3.175*20°*0.1 * 1 3.175*20°*0.2 * 1 3.175*20°*0.3 * 1
2	Water pump fixed feet * 8	6	USB connect cable * 1		
3	Water pump inlet * 2	7	Spanner * 2		
4	Clamp tool * 6	8	Water sink outlet pipe * 1		
Packing		110*80*85cm Wooden box		Weight	138KG

CNC6040 **4 axis machine**, We send the 4th axis with 3 axis machine's spare parts together :

Configuration(for option)	Type	Pic
Standard	Stepper motor	
High	Servo motor	
Packing		110*80*85cm Wooden box
Weight		143KG