

## Packing list for CNC 6040





## Packing list

- 1 water pump \*1
- 2 CD (software) \*1( Optional )
- 3 Fixed bracketing \*4
- 4 milling bit \*1
- 5 clamp tool \*3
- 6 parallel cable \*1
- 7 USB cable \*1 ( Optional )
- 8 auto-checking tool \*1
- 9 clamp tool \*6
- 10 engraving bit \*3
- 11 collet 3.175 \*1
- 12 screws \*4
- 13 limited switch \*4

Packing: 60\*52\*43cm / 80\*22\*63 cm ,weight: 60KG,carton.